

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

FIG 1




FIG 2




Fig. 3





Fig 4



Title: LIGHT-EMITTING  
CEILING TILE  
Inventor(s): Paul Thurk  
DOCKET NO.: 040897-0114

FIG. 5





FIG. EIGHTY-EIGHT  
CEILING TILE  
Inventor(s): Paul Thurk  
DOCKET NO.: 040897-0114

FIG. 6



LIGHT EMITTING  
CEILING TILE  
Inventor(s): Paul Thurk  
DOCKET NO.: 040897-0114




FIG. 7